

# Interim Reclamation Inspection

September 10, 2018

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 440510

Inspection Document #: 682404002

Weld County, CO

SESE Section 24 T6N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BURR FD PAD /23-219HN  
Location ID: 440510



**Photo 1.** Photo taken from the northern interim reclamation area, facing Northwest. Photo illustrates a section with little to no crop growth in the interim area.