

Inspection Photos

09/11/2018

Operator: MONAHAN* REX FAMILY TRUST -
59100

Location ID: 387471

Inspection Doc. Number: 682503878
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 387471



Photo 1: 1998 Google Earth aerial imagery. Photo shows areas of a possible battery site, the flowline observed within the diversion canal, the two risers and the location of the Atwood East Unit #5-1 well.



Photo 2: Most current available Google Earth Aerial imagery (2015). Photo shows areas of a possible battery site, the flowline observed within the diversion canal, the two risers and the location of the Atwood East Unit #5-1 well.



Photo 3: Photo taken at coordinates 40°33'10.81"N, 103°14'40.52"W, facing southeast. Photo shows area where flowline becomes exposed at the surface, and crosses the canal. Photo also shows area of the risers.



Photo 4: Photo taken at coordinates 40°33'10.81"N, 103°14'40.52"W. Photo shows area where flowline becomes exposed at the surface, and crosses the canal.



Photo 5: Photo taken at coordinates 40°33'10.81"N, 103°14'40.52"W. Complainant had expressed concerns and indicated that flowline collects various debris (wood, plant matter, trash, etc...) that could be a potential threat to the integrity of the canal and results in regular maintenance



Photo 6: Photo taken at coordinates 40°33'10.81"N, 103°14'40.52"W, facing southeast. Photo shows two risers remaining on the site.