

Inspection Photos

09/14/2018

Operator: DIVERSIFIED OPERATING
CORPORATION - 24461

Location ID: 408318

Inspection Doc. Number: 682503906
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northeast end of the location, facing west. Photo shows large areas of the location that remains predominantly bare and exposed soil with ongoing erosion issues.



Photo 2: Photo taken from the north end of the location, facing southwest. Photo shows large areas of the location that remains predominantly bare and exposed soil with ongoing erosion issues.



Photo 3: Photo taken from the northwest end of the location, facing east. Photo shows large areas of the location that remains predominantly bare and exposed soil with ongoing erosion issues.



Photo 4: Photo taken from the northwest end of the location, facing southeast. Photo shows large areas of the location that remains predominantly bare and exposed soil with ongoing erosion issues.



Photo 5: Continued from photo 4. Photo shows erosion degradation occurring on location. 6 foot measuring stick for reference.



Photo 6: Photo taken from the north end of the location, facing south. Photo shows erosion degradation occurring on location. 6 foot measuring stick for reference.