

# Inspection Photos

09/14/2018

Operator: DIVERSIFIED OPERATING  
CORPORATION - 24461

Location ID: 409213

Inspection Doc. Number: 682503908  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the east end of the location, facing west. Photo shows large areas of the location remains bare and exposed soil.

Inspection Photos  
Operator: DIVERSIFIED OPERATING CORPORATION - 24461  
Location ID: 409213



**Photo 2:** Photo taken from the east end of the location, facing east. Photo shows large areas of the location remains bare and exposed soil.




09.14.2018

**Photo 3:** Photo taken from the adjacent reference area, facing south. Photo shows vegetation on the reference area to compare to the disturbance area.



**Photo 4:** Photo taken from the former access road, facing south. Photos 4-6 show and overview of the gallery erosion that has formed along the access road. Photo shows erosion has not been reclaimed.



**Photo 5:** Photo of gully erosion.



**Photo 6:** Photo of gully erosion.