

**Inspection Photo**  
**Savage 1-32**  
**API # 045-07201**  
**Inspection # 689301947**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo**  
**Savage 1-32**  
**API # 045-07201**  
**Inspection # 689301947**



**Location Photo #3, patch failed**



**Location Photo #4, hole in liner near stairs**

**Inspection Photo**  
**Savage 1-32**  
**API # 045-07201**  
**Inspection # 689301947**



**Location Photo #5, Heavy erosion along access road**



**Location Photo #6, Heavy erosion along access road.**