

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2018

Submitted Date:

09/12/2018

Document Number:

689401590**FIELD INSPECTION FORM**

Loc ID 334426	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	Status Summary:
2A Doc Num: _____			<input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information:			Findings: <div style="border-bottom: 1px solid black; margin-bottom: 5px;">33</div> <div style="border-bottom: 1px solid black; margin-bottom: 5px;">1</div> <input checked="" type="checkbox"/> Corrective Action Response Requested
OGCC Operator Number: <u>10433</u>			
Name of Operator: <u>LARAMIE ENERGY LLC</u>			
Address: <u>1401 SEVENTEENTH STREET #1400</u>			
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>	

Contact Information:

Contact Name	Phone	Email	Comment
Laramie Energy LLC		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298709	WELL	PR	01/20/2017	OW	077-09756	Gunderson 29-05E	PR
299043	WELL	PR	01/20/2017	OW	077-09758	Gunderson 29-06E	PR
299044	WELL	PR	11/28/2016	OW	077-09759	Gunderson 29-07E	PR
299045	WELL	PR	12/05/2016	OW	077-09760	Gunderson 29-08E	PR
299046	WELL	PR	02/01/2017	OW	077-09761	Gunderson 29-08M	PR
299047	WELL	PR	12/10/2016	OW	077-09762	Gunderson 29-09E	PR
299048	WELL	PR	02/02/2017	OW	077-09763	Gunderson 29-09M	PR
299049	WELL	PR	12/08/2016	OW	077-09764	Gunderson 29-10E	PR
299050	WELL	PR	02/11/2017	OW	077-09765	Gunderson 29-10M	PR
299051	WELL	PR	02/10/2017	OW	077-09766	Gunderson 29-11M	PR
299053	WELL	PR	08/30/2017	OW	077-09767	Gunderson 29-04E	PR
299054	WELL	PR	11/01/2016	OW	077-09768	Gunderson 29-11E	PR
299055	WELL	PR	01/15/2017	OW	077-09769	Gunderson 29-12E	PR
439999	WELL	PR	02/14/2017	GW	077-10225	Gunderson 29-13M	PR
440000	WELL	PR	02/03/2017	GW	077-10226	Gunderson 29-14M	PR
440001	WELL	PR	02/05/2017	GW	077-10227	Gunderson 29-15M	PR
440002	WELL	PR	02/15/2017	GW	077-10228	Gunderson 29-12M	PR
440003	WELL	PR	01/18/2017	GW	077-10229	Gunderson 29-16E	PR
440004	WELL	PR	02/04/2017	GW	077-10230	Gunderson 29-14E	PR
440005	WELL	PR	10/23/2017	GW	077-10231	Gunderson 29-13E	PR
440006	WELL	PR	01/20/2017	GW	077-10232	Gunderson 29-15E	PR
449130	WELL	PR	07/28/2017	GW	077-10358	Piceance Federal 29-18W	PR
449131	WELL	PR	07/25/2017	GW	077-10359	Piceance Federal 29-19E	PR
449132	WELL	PR	07/22/2017	GW	077-10360	Piceance Federal 29-21E	PR

449133	WELL	PR	07/27/2017	GW	077-10361	Piceance Federal 29-22E	PR
449134	WELL	PR	07/24/2017	GW	077-10362	Piceance Federal 29-17E	PR
449135	WELL	PR	07/27/2017	GW	077-10363	Piceance Federal 29-20E	PR
449136	WELL	PR	07/20/2017	GW	077-10364	Piceance Federal 29-18E	PR

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Posted Emergency Contact Number 1-800-891-6191](#)Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused tank in earth containment.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/12/2018

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities									
Facility ID:	298709	Type:	WELL	API Number:	077-09756	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299043	Type:	WELL	API Number:	077-09758	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299044	Type:	WELL	API Number:	077-09759	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299045	Type:	WELL	API Number:	077-09760	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299046	Type:	WELL	API Number:	077-09761	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299047	Type:	WELL	API Number:	077-09762	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299048	Type:	WELL	API Number:	077-09763	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299049	Type:	WELL	API Number:	077-09764	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			

Facility ID:	299050	Type:	WELL	API Number:	077-09765	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299051	Type:	WELL	API Number:	077-09766	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299053	Type:	WELL	API Number:	077-09767	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299054	Type:	WELL	API Number:	077-09768	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	299055	Type:	WELL	API Number:	077-09769	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	439999	Type:	WELL	API Number:	077-10225	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	440000	Type:	WELL	API Number:	077-10226	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	440001	Type:	WELL	API Number:	077-10227	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			

Facility ID:	440002	Type:	WELL	API Number:	077-10228	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	440003	Type:	WELL	API Number:	077-10229	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	440004	Type:	WELL	API Number:	077-10230	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	440005	Type:	WELL	API Number:	077-10231	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	440006	Type:	WELL	API Number:	077-10232	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	449130	Type:	WELL	API Number:	077-10358	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	449131	Type:	WELL	API Number:	077-10359	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	449132	Type:	WELL	API Number:	077-10360	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			

Facility ID: 449133 Type: WELL API Number: 077-10361 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 449134 Type: WELL API Number: 077-10362 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 449135 Type: WELL API Number: 077-10363 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 449136 Type: WELL API Number: 077-10364 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Stormwater erosion appears to be controlled on the location at this time.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401760476	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4576662
689401595	Gunderson 29-09 Pad Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4576660