

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28SWNE

Location #: 323513



Photo #1

Sooner Unit 7-28 (API # 05-123-13138) wellhead

Bradenhead NOT plumbed to surface

Stained soil



Photo #2

Sooner Unit 7-28 wellsite

Stained soil – pump jack skid



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28SWNE

Location #: 323513



Photo #3

Sooner Unit 7-28 wellsite

Unused equipment



Photo #4

Sooner Unit 7-28 wellsite

Unused equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28SWNE

Location #: 323513



Photo #5

Sooner Unit Battery

