

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWNE

Location #: 323461



Photo #1

Sooner Unit 2-28 (API # 05-123-13065) wellhead

Bradenhead NOT plumbed to surface



Photo #2

Sooner Unit 2-28 wellsite

Sign not legible

Emergency number not legible

Unused equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWNE

Location #: 323461



Photo #3

Sooner Unit 2-28 Pump jack - gearbox

Stained soil



Photo #4

Sooner Unit 2-28 Pump jack

Unused equipment – belt guards



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 28NWNE

Location #: 323461



Photo #5

Sooner Unit Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources