

Inspection Photos

Location Name: Sooner Unit - 68N58W / 21SESE

Location #: 330359



Photo #1

Sooner Unit 21-16-9 wellhead
Bradenhead NOT plumbed to surface
Stained soil
From previous FIR



Photo #2

Sooner Unit 21-16-9 (API # 05-123-18968) wellhead
Bradenhead NOT plumbed to surface
Stained soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sooner Unit - 68N58W / 21SESE

Location #: 330359



Photo #3

Sooner Unit Battery

