

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W / 21SENW

**Location #:** 330509



**Photo #1**

**Sooner Unit 21-6-15** (API # 05-123-19226) wellhead

**Bradenhead NOT plumbed to surface**

**Stained soil**



**Photo #2**

**Sooner Unit 21-6-15** (API # 05-123-19226) wellsite

**New sign**

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W / 21SENW

**Location #:** 330509



**Photo #3**

**Sooner Unit 21-6-15** (API # 05-123-19226) wellsite

**Stained soil**

**Unused Equipment**



**Photo #4**

**Sooner Unit 21-6-15** (API # 05-123-19226) wellsite

**Unused Equipment**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

**Location Name:** Sooner Unit - 68N58W / 21SENW

**Location #:** 330509



**Photo #5**

***Sooner Unit*** Battery

