

Inspection Photos

Operator: BP Production

API: 05-067-09567

Date: 9/13/2018



Photo 1. View of the project area from the northern edge facing center. Well pad is recontoured, seeded, and mulched.



Photo 2. View of the western portion of the project area from the northern edge facing southwestward.



Photo 3. View of the western portion of the project area from the northern edge facing southeastward.



Photo 4. View of the portion of the project area where desirable vegetation is becoming established, largely comprised of blue grama (*Bouteloua gracilis*), western wheatgrass (*Pascopyrum smithii*), and smooth brome (*Bromus inermis*).



Photo 5. View of portion of project area where revegetation is sparse. This should be monitored and spot-seeding applied if vegetative cover is not increasing in sparse areas.



Photo 6. View of Canada thistles (*Cirsium arvense*) in the eastern project area.



Photo 7. View musk thistles (*Carduus nutans*) in the southern project area.



Photo 8. View of another musk thistle in seedling condition within the project area.