

SG 22-27 Pad
API# 05-045-14473
Inspection# 689701814



Entrance photo. Dead weed debris.



Dead weed debris on location.



Dead weed debris on location.



Erosion channel in ditch.



Sediment build up in ditch behind tank battery.



Sediment build up and dead weed debris in ditch behind tank battery.