

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2018

Submitted Date:

09/19/2018

Document Number:

692600357**FIELD INSPECTION FORM**

Loc ID 417852 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417857	WELL	PR	09/05/2010	GW	125-11882	White 44-03 1S46W	PR

General Comment:[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at meter shed		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Metal panels around meter shed and VGS		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried by meter shed		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Weatherford unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Kohler gas engine		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	417857	Type:	WELL	API Number:	125-11882	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT