

Inspection Photos

Location Name: Federal Wildhorse - 68N58W / 31SWSE

Location #: 322954



Photo #1

Federal Wildhorse 15-31 (API # 05-123-12324)
wellhead

From previous FIR



Photo #2

Federal Wildhorse 15-31 wellhead sign

From previous FIR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Wildhorse - 68N58W / 31SWSE

Location #: 322954



Photo #3

Federal Wildhorse 15-31 Battery

Heavy Weeds

From previous FIR



Photo #4

Federal Wildhorse 15-31 Battery

Weeds have been cut

Appear to be dispersing



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Wildhorse - 68N58W / 31SWSE

Location #: 322954



Photo #5

Federal Wildhorse 15-31 Crude oil tank

NFPA placard numbers illegible

From previous FIR



Photo #6

Federal Wildhorse 15-31 Battery

NFPA placard numbers now legible



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Wildhorse - 68N58W / 31SWSE

Location #: 322954



Colorado Oil & Gas Conservation Commission
40.61103, -103.9014, 1447.0m, 353°
2018/08/27 03:29:50 PM

Photo #7

Federal Wildhorse 15-31 separator

NFPA placard numbers illegible

From previous FIR



Photo #8

Federal Wildhorse 15-31 Battery

NFPA placard numbers now legible



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Wildhorse - 68N58W / 31SWSE

Location #: 322954



Photo #9

Federal Wildhorse 15-31 GSM

No Display / No recent calibration date



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources