

Inspection Photos

Operator: DJ Simmons

API: 05-033-40001

Date: 9/18/2018



Photo 1. View of equipment that remains within the project area.



Photo 2. View of wood debris and trash in the project area.



Photo 3. View of access road still in place from well pad facing eastward.



Photo 5. View of reference area from the southern portion of the project area facing southward. Crop field surrounds the project area.