



Photo#1:
Overview of Location to Northwest.

September 12,2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Coseka Res PA Bolton Draw API#057-06251



Photo#2:
View Southeast over Location Center



Photo#3:
View Southwest over Location Center

September 12,2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Coseka Res PA Bolton Draw API#057-06251