

# *Inspection Photos*

*Loc#451938*

*Operator: Sandridge*

*Inspection Number: 692400140*

*Inspection Date: 9/14/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#1:**  
Overview of Location from entry to Northwest.

September14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Beaver Creek Loc#451938



Photo#2:

Noxious weed, Canada thistle is established along site perimeters, between berms and fencing.

September 14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Beaver Creek Loc#451938





Photo#3:

Non Noxious weeds are senescing & dead along site perimeters, between berms and fencing. Note Wattles that have become Debris in Photo#4.



Photo#4:

September14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Beaver Creek Loc#451938





**Photo#5:**

Wattles installed at access road corner turn into Pad have been dislodged & damaged.

September14, 2018



**Photo#6:**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Beaver Creek Loc#451938



**Photo#7:**  
Topsoil pile at South portion of site needs further stabilization & protection.

September14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Beaver Creek Loc#451938