

Inspection Photos
Location Name: GREEN #1
Location ID: 319921



PHOTO 1: Wellhead



PHOTO 2: Tank battery

Inspection Photos
Location Name: GREEN #1
Location ID: 319921



PHOTO 3: Weeds piled west of pumpjack



PHOTO 4: Trash on location

Inspection Photos
Location Name: GREEN #1
Location ID: 319921



PHOTO 5: Weeds near crude oil tank



PHOTO 6: Weeds near produced water tank