

Inspection Photos

Operator: DJ Simmons

Facility ID: 438969

Date: 9/18/2018



Photo 1. View of tank battery in the northern project area.



Photo 2. View of riser in the northwestern project area. Surface owner states that two tanks in the background are his.



Photo 3. View of risers and other facilities in the southeastern project area.



Photo 4. Closeup view of risers and other equipment in the southeastern project area. These do not appear to be in use.



Photo 5. View of project facilities still in place, appear to be in operation.



Photo 6. View of trash storage and oil and gas equipment in the southwestern portion of the project area.



Photo 7. View of what appears to be old tank battery location still in place. Risers and gas lines still in place need proper abandonment.



Photo 8. View of the western portion of the project area. Some project facilities appear to be functioning.