

Inspection Photos

09/20/2018

Operator: PETRO-CANADA RESOURCES (USA)
INC - 72085

Location ID: 394508

Inspection Doc. Number: 682503927
Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the south end of the location, facing northwest. Photo shows location remains predominantly bare and exposed soil.



Photo 2: Photo taken from the south end of the location, facing north. Photo shows location remains predominantly bare and exposed soil.



Photo 3: Photo taken from the south end of the location, facing east. Photo shows location remains predominantly bare and exposed soil.



Photo 4: Photo taken from the east end of the location, facing west. Photo shows location remains predominantly bare and exposed soil.



Photo 5: Photo taken from the center of the location. Photo shows location remains predominantly bare and exposed soil.



Photo 6: Photo taken from the adjacent reference area. Photo shows vegetation over the reference area. Photo shows location is not reflective of the reference area.