

Inspection Photos  
Location Name: Duncan B-12  
API: 05-081-07075



**Photo 1. Overview of location taken at entrance facing southeast.**



**Photo 2. Tank labeled with two different contents and no capacity; dried annual weeds immediately adjacent to berm.**