


99999999

# L & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

NOTICE OF UNSATISFACTORY INSPECTION

NOTICE OF SATISFACTORY INSPECTION



1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100


API No. 05-	<i>121 - 10402</i>	LEASE NAME:	<i>Walter Runne I</i>
LOCATION:	<i>SESE 35-2N-53</i>	OPERATOR:	<i>VIS OP</i>
DATE:	<i>12-4-95</i>	INSPECTOR:	<i>Binkley</i>
Insp. Type: <i>SR</i>	Insp. Status: <i>PA</i>	PA: <input checked="" type="radio"/> Y <input type="radio"/> N	Pass/Fail: <input checked="" type="radio"/> P <input type="radio"/> F
		Viol.: Y <input checked="" type="radio"/> N	NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)		
<b>Fences</b> (Rule 604.C.(3), 1003.A)		
<b>Tank Battery Equipment</b> (Rule 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 604)		
<b>General Housekeeping</b> (Rule 603.G)		
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)	<i>Cultivated</i>	
<b>Miscellaneous</b>		

### CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:



This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site



00047966