



ORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- 123 - 05885		LEASE NAME: Harm #1	
LOCATION: SW-SW 8-11N-59		OPERATOR: Ron Soper	
DATE: 3-1-96		INSPECTOR: EBB Bailey	
Insp. Type: PR	Insp. Status: PR	PA: Y N	Pass/Fail: P <u>E</u> Viol. <u>Y</u> <u>N</u> NOV: Y <u>N</u>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	ok	
Pits (Reserve/Production) (Rule 902, 903, 904)	100x200 metal skin	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)	Sys, VT, 2-300	
Fire Walls/Berms/Dikes (Rule 604)	No tank berms	
General Housekeeping (Rule 603.G)	ok	
Spills (Oil/Water) (Rule 908)	slight oily soil	
Bradenhead (Rule 207)	pump off	
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous		



CORRECTIVE ACTION REQUIRED: Cultivate oily soil, install tank berms, submit form 4, status.

Date Corrective Action Required By: 3-30-96

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

Discussed w/ Ron. EB