

Inspection Photos

09/24/2018

Operator: SCHNEIDER ENERGY SERVICES INC -
#76840

Location ID: 317245

Inspection Doc. Number: 682503956
Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the west end of the well location, facing northeast. Photo shows well location remains predominantly bare and exposed soil.



Photo 2: Photo taken from the west end of the well location, facing east. Photo shows well location remains predominantly bare and exposed soil.



Photo 3: Photo taken from the west end of the well location, facing southeast. Photo shows well location remains predominantly bare and exposed soil.



Photo 4: Photo taken the well location, facing north. Photo shows area of the well that has not been recontoured/regraded, and gravel remains.



Photo 5: Continued from photo 4.



Photo 6: Photo taken from the well location, facing west. Photo shows access road remains evident. Additional reclamation required.



Photo 7: Photo taken from the southwest corner of the pit and facility location, facing north. Photo shows pits appear to have been closed, equipment removed and reclamation in process.



Photo 8: Photo taken from the southwest corner of the pit and facility location, facing east. Photo shows pits appear to have been closed, equipment removed and reclamation in process.



Photo 9: Photo taken from the south end of the pit and facility location, facing north. Photo shows area of the location where subsidence appears to be forming.



Photo 10: Photo taken from the pit and facility location. Photo shows debris remaining on location.



Photo 11: Photo taken from the pit and facility location. Photo shows debris remaining on location.