



COLORADO OIL & GAS CONSERVATION COMMISSION
OIL-WATER SPILL/CITIZEN COMPLAINT INSPECTION FORM

Location NW 1/4 - S9 - E10 - T66W Field Kattandeg
Operator Genex Petroleum County Weld
Well Name McClusky 11-9 API # 123-11683
Person reporting spill/complaint: Dave Dillon
Date of occurrence: 12-22-95
Date of complaint: 12-22-95
Phone #: 364-0038
351-0023

Address: _____

Follow up by phone: Date 12-22-95
Contact Jersey McClusky

Follow up by field visit: Date 12-22-95
Contact Harold of Genex

Type of spill/overflow: N/A
Estimated volume of fluid: _____
Affected area: _____

Did spill/overflow reach waters of the state? Yes _____ No _____

Remedial action: Sundry notice required - Yes _____ No _____
(Rule 329) How was spill/overflow cleaned up? _____

Comments: Landowner complained of tree
limbs not being removed. Dave
Dillon asked Linda Powell to inspect
location and see if Genex had cleared
location - Everything was gone
when Linda arrived