

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2018

Submitted Date:

09/28/2018

Document Number:

691200517**FIELD INSPECTION FORM**
 Loc ID 326915 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|--|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |
| Arthur, Denise | | denise.arthur@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 246058 | WELL | PR | 07/01/2018 | GW | 123-13855 | FOOSE A18-10 | SI |

General Comment:[This is a WELL inspection. Refer to FIR #691200513 dated 9/27/2018 for Battery info.](#)

| Location | | | |
|--|---|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | L | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | CONTAINERS | | |
| Comment: | Methanol drum at well is placarded. | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Weeds around wellsite. Statewide unused equipment, weeds, waste, and trash requirements. Weeds (10 days). Refer to Rule 603.f for guidance. | | |
| Corrective Action: | Remove, manage, & control weeds around wellsite. Comply with Rule 603.f . | | Date: 10/08/2018 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No _____ | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Methanol pump & drum w/ drip tray at wellsite. | | |
| Corrective Action: | | | Date: |
| Type: | # | | |
| Comment: | Refer to FIR #691200513 dated 9/27/2018 for additional Equipment info. | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|---------------------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| | | | CENTRALIZED BATTERY | | 40.485120,-104.584187 | |
| Comment: | This Centralized Battery serves 3 locations (420665, 326702, 326915). Refer to FIR #691200513 dated 9/27/2018 for Tanks & Berms info. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 246058 Type: WELL API Number: 123-13855 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: SI. Wellhead master valve is shut & chained. Plunger lift lubricator wing valves are shut. COGCC records indicated PR in 07/2018. Showed SI from 9/2017 through 6/2018. No further records online.Corrective Action: Date: **BradenHead**Comment: Bradenhead appears plumbed to surface.Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 691200518 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592249 |