

**Inspection Photo**  
**Rifle Boulton 1**  
**API # 045-06127**  
**Inspection # 689301993**



**Location Photo #1**



**Location Photo #2, Missing wellhead sign.**



**Inspection Photo**  
**Rifle Boulton 1**  
**API # 045-06127**  
**Inspection # 689301993**



**Location Photo #3, Inaccurate battery sign.**



**Location Photo #4, Uncontrolled weeds in battery containment.**



**Inspection Photo**  
**Rifle Boulton 1**  
**API # 045-06127**  
**Inspection # 689301993**



**Location Photo #5, Uncontrolled weeds in battery containment.**



**Location Photo #6, Unused equipment.**



**Inspection Photo**  
**Rifle Boulton 1**  
**API # 045-06127**  
**Inspection # 689301993**



**Location Photo #7, Unused equipment.**