

Inspection Photos
Location Name: Bonifacio Gallegos A #1
API: 05-067-07870



Bonifacio Gallegos A #1 location photo.



Bonifacio Gallegos A #1 well head and pump jack.

Inspection Photos
Location Name: Bonifacio Gallegos A #1
API: 05-067-07870



Valve station.



Lube oil leak on east side of pump jack.