

# Inspection Photos

Operator: BP America

API: 05-067-08882

Date: 9/25/2018



**Photo 1. View of the project area from the northeastern corner facing center.**





**Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and dropseed (*Sporobolus* sp.).**





**Photo 3. View of the western project area from the northwestern corner facing southward.**





**Photo 4. View of erosional channel up to 2.5 feet wide and deep, in the southwestern project area.**