



ADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

C

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 001 - 09115-1		LEASE NAME: Christiansen 12-9	
LOCATION: SW NW 9-15-67W		OPERATOR: HS Resources	
DATE: 10/3/96		INSPECTOR: LAR	
Insp. Type: PR	Insp. Status: PR	PA: Y N	Pass/Fail: P (F) Viol.: (Y) N NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	Well Sign posted at battery	
Pits (Reserve/Production) (Rule 902, 903, 904)	(1) buried 70 bbl steel tank	
Fences (Rule 604.C.(3), 1003.A)	Well, battery & prod facility fenced	
Tank Battery Equipment (Rule 604)	(1) 300 bbl prod tank (1) GMR (1) separator	
Fire Walls/Berms/Dikes (Rule 604)	Berm in good condition	
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: Post wellsign at well (some distance from) tank battery

Date Corrective Action Required By: 11/3/96

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.