

Inspection Photo
Pitman 13-3A
API # 045-09551
Inspection # 689302030



Location Photo #1



Location Photo #2

Inspection Photo
Pitman 13-3A
API # 045-09551
Inspection # 689302030



Location Photo #3, unused equipment.



Location Photo #4, stained rock in battery containment.

**Inspection Photo
Pitman 13-3A
API # 045-09551
Inspection # 689302030**



Location Photo #5, Missing tank information



Location Photo #6, Missing tank information

**Inspection Photo
Pitman 13-3A
API # 045-09551
Inspection # 689302030**



Location Photo #7, Missing tank information



Location Photo #8, Holes in secondary containment.

**Inspection Photo
Pitman 13-3A
API # 045-09551
Inspection # 689302030**



Location Photo #9, Holes in secondary containment.



Location Photo #10, Holes in secondary containment.

Inspection Photo
Pitman 13-3A
API # 045-09551
Inspection # 689302030



Location Photo #11, Holes in secondary containment.



Location Photo #12, Holes in secondary containment.