

Final Reclamation Inspection

September 27, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-23921

Inspection Document #: 682404015

Weld County, CO

SESE Section 24 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DESHAZO #24-44
API: 05-123-23921



Photo 1. Photo taken from the battery location, facing West. Battery location is not in compliance with Rule 1004 standards. Mostly bare soil with little to no desirable vegetation was observed.



Photo 2. Photo taken from the battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: DESHAZO #24-44
API: 05-123-23921



Photo 3. Reference photo taken west of the battery location, facing West.



Photo 4. Photo taken from the well location access road, facing East. Appears a recent disturbance (tenant farmer) may have occurred. Appears the farmer may be using the former road to access the crop field.