

Inspection Photos
Location Name: Schug Harland K 1
Location ID: 319991



Photo 1 WH

Photo 2 TNK BTRY

Inspection Photos
Location Name: Schug Harland K 1
Location ID: 319991



Photo 3 Unused PU



Photo 4 Erosion under 300BBL oil tank

Inspection Photos
Location Name: Schug Harland K 1
Location ID: 319991



Photo 5 Stained soil and trash around crude oil tank



Photo 6 Stained soil and trash around crude oil tank

Inspection Photos
Location Name: Schug Harland K 1
Location ID: 319991



Photo 7 Unused equipment outside of sep

Photo 8 unused equipment and trash inside sep

Inspection Photos
Location Name: Schug Harland K 1
Location ID: 319991



Photo 9 stained soil improper tank lid

Photo 10 improper lid

Inspection Photos
Location Name: Schug Harland K 1
Location ID: 319991



Colorado Oil and Gas Conservation Commission
39.95857, -103.75402, 1390.3m
Oct 2, 2018 15:40:43

Photo 11 Loc pic