

Inspection Photos

10/02/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 431817

Inspection Doc. Number: 682503969

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the east end of the two PR wells on location, facing west. Photo shows well API 123-36799 in foreground, and well 123-36800 in background. Photo also shows that the AL well 123-36831 does not appear to have been drilled.



Photo 2: Photo taken from the PR wells, facing southwest. Photo shows that the AL well 123-36831 does not appear to have been drilled.



Photo 3: Photo taken from the northwest corner of the location, facing east. Photo shows vegetation over the interim area.



Photo 4: Photo taken from the northwest corner of the location, facing south. Photo shows vegetation over the interim area.



Photo 5: Photo taken from the south end of the tank battery facility, facing west. Photo shows areas where Canada Thistle rosettes were observed. This is a Colorado State listed noxious weed that needs to be managed.



Photo 6: Continued from photo 5. Photo shows Canada Thistle rosettes. This is a Colorado State listed noxious weed that needs to be managed