


Location Name: Alfred Ward & Son Operating – Colo State B #3
Inspection Date: 9/26/2018



Photo # - 1



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Alfred Ward & Son Operating – Colo State B #3
Inspection Date: 9/26/2018



Photo # - 2

Wellhead viewing north



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Alfred Ward & Son Operating – Colo State B #3
Inspection Date: 9/26/2018



Photo # - 3

Wellhead viewing east



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Alfred Ward & Son Operating – Colo State B #3
Inspection Date: 9/26/2018



Photo # - 4

Oil on water at wellhead, gas bubbling to surface



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Alfred Ward & Son Operating – Colo State B #3
Inspection Date: 9/26/2018



Photo # - 5

View south toward wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Alfred Ward & Son Operating – Colo State B #3
Inspection Date: 9/26/2018



Photo # - 6

View northeast toward wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Alfred Ward & Son Operating – Colo State B #3
Inspection Date: 9/26/2018



Photo # - 7

Small pond west of wellhead and access road



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources