

Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302044



Location Photo #1,

Location Photo #2,

Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302044



Location Photo #3,



Location Photo #4 uncontrolled weeds on location.

Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302044



Location Photo #5, uncontrolled weeds on location.

Location Photo #6, uncontrolled weeds near separators.

**Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302044**



Location Photo #7, uncontrolled weeds near separators.



Location Photo #8, uncontrolled weeds near tank battery.



Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302044



Location Photo #9, uncontrolled weeds near tank battery.



Location Photo #10, uncontrolled weeds.

**Inspection Photo
Savage RWF 521-26
API # 045-15945
Inspection # 689302044**



Location Photo #11, Missing tank volume



Location Photo #12, missing tank volume.