

Inspection Photo
Savage 1-26-6-94 W
API # 045-07676
Inspection # 689302048



Location Photo #1,



Location Photo #2, uncontrolled weeds on location.