

Inspection Photo
Savage RMV 121-27
API # 045-07680
Inspection # 689302050



Location Photo #3



Location Photo #4, unused equipment near tank battery.

Inspection Photo
Savage RMV 121-27
API # 045-07680
Inspection # 689302050



Location Photo #5, uncontrolled weeds on location



Location Photo #6, uncontrolled weeds on location