

Well Name : Elsa 34-6-19 1

API # : 067-09922



Photo 1: Wellhead sign.



Photo 2: Wellhead sign.

Well Name : Elsa 34-6-19 1
API # : 067-09922



Photo 3: Impacted soil and gravel spot.



Photo 4: Impacted soil and gravel spot.

Well Name : Elsa 34-6-19 1

API # : 067-09922



Photo 5: Impacted soil and gravel spot.



Photo 6: Unmarked anchor.

Well Name : Elsa 34-6-19 1

API # : 067-09922



Photo 7: Animal burrow in berm.



Photo 8: Animal burrow exit point on fill slope with erosion channel.

Well Name : Elsa 34-6-19 1

API # : 067-09922



Photo 9: Lube oil tank with no spill prevention.



Photo 10: Lube oil tank with no spill prevention.