

Location Name: Alfred Ward & Son Operating – Blomenkamp #4
Inspection Date: 9/26/2018



Photo # - 1

121-05567



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Alfred Ward & Son Operating – Blumenkamp #4
Inspection Date: 9/26/2018



Photo # - 2

View east-southeast at wellhead, oily soil adjacent to wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Alfred Ward & Son Operating – Blumenkamp #4
Inspection Date: 9/26/2018



Photo # - 3

Oily soil adjacent to wellhead



Location Name: Alfred Ward & Son Operating – Blomenkamp #4
Inspection Date: 9/26/2018



Photo # - 4

View west of wellhead



Location Name: Alfred Ward & Son Operating – Blumenkamp #4
Inspection Date: 9/26/2018



Photo # - 5

Tire track and shrinkage cracks west of wellhead



Location Name: Alfred Ward & Son Operating – Blomenkamp #4
Inspection Date: 9/26/2018



Photo # - 6

Tire tracks in sedges west of wellhead, view south

