

Location Name: Fritzler Resources, Inc. (Decker B 1 121-05140) Rem #8509
Inspection Date: 8/01/2018



08.01.2018

Photo # - 1

Location Name: Fritzler Resources, Inc. (Decker B 1 121-05140) Rem #8509
Inspection Date: 8/01/2018



Photo # - 2

View northwest across former landfarm area, weed control needed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Fritzler Resources, Inc. (Decker B 1 121-05140) Rem #8509
Inspection Date: 8/01/2018



Photo # - 3

View west across former landfarm area, weed control needed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Fritzler Resources, Inc. (Decker B 1 121-05140) Rem #8509

Inspection Date: 8/01/2018



Photo # - 4

View northeast across production pits



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Fritzler Resources, Inc. (Decker B 1 121-05140) Rem #8509
Inspection Date: 8/01/2018



Photo # - 5

View eastsoutheast across production pits



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Fritzler Resources, Inc. (Decker B 1 121-05140) Rem #8509
Inspection Date: 8/01/2018



Photo # - 6

View southwest at former oil skim pit area and production equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources