

Inspection Photos
Location Name: Walker 3-2
API: 05-081-07096



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Unmarked risers.