

Inspection Photos
Location Name: Saratoga 44-3
API: 05-081-07349



Photo 1. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: Saratoga 44-3
API: 05-081-07349



Photo 2. Unmarked risers.



Photo 3. Unmarked riser.

Inspection Photos
Location Name: Saratoga 44-3
API: 05-081-07349



Photo 4. Unmarked risers.



Photo 5. Unmarked riser.