

Inspection Photos

Operator: BP America

API: 05-067-06973

Date: 9/25/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing center.



Photo 3. View of erosional channel approximately 1.5 feet wide and 8 inches deep in the eastern fill slope. Stabilization measures are needed here.



Photo 4. View of approximately 200 Canada thistles (*Cirsium arvense*) within the southeastern project area where concentrated stormwater flows off of the working area.