

# Interim Reclamation Inspection

October 4, 2018

Operator: EXTRACTION OIL & GAS LLC- #10459

Location ID: 442759

Inspection Document #: 682404044

Weld County, CO

Lot 2 Section 31 T7N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Hester Farms /31-H Pad  
Location ID: 442759



Google Earth aerial imagery taken October 14, 2017 illustrating the Hester Farms Location. The location and Modular Large Volume Tank (MLVT) area are not in compliance Rule 1003 standards.

Inspection Photos  
Location Name: Hester Farms /31-H Pad  
Location ID: 442759



**Photo 1.** Photo taken from the northern interim area, facing West. Little to no germination of desirable species was observed. Photo illustrates weedy, annual species of Chenopodiaceae. Operator need to control and manage weeds.



**Photo 2.** Photo taken from the northern interim area, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: Hester Farms /31-H Pad  
Location ID: 442759



**Photo 3.** Photo taken from the entrance of the location, facing Southwest. See comments under Photo 1.



**Photo 4.** Photo taken from the southeastern location, facing Southwest. See comments under Photo 1.



Inspection Photos  
Location Name: Hester Farms /31-H Pad  
Location ID: 442759



**Photo 5.** Photo taken from the southeastern MLVT area. Photo illustrates an example of a List B Colorado Noxious Canada thistle, a List B Colorado Noxious, which has already seeded out. Germination of desirable species was observed throughout the MLVT area.



**Photo 6.** Photo taken from the eastern MLVT area, facing North. Photo illustrates unused equipment.