

Inspection Photos
Location Name: DNR Hartman State 11-16
Location ID: 320317



Photo 1 WH stained soil

Photo 2 Stained soil

Inspection Photos
Location Name: DNR Hartman State 11-16
Location ID: 320317



Photo 3 WH Stained Soil

Photo 4 Produced water tank no placards

Inspection Photos
Location Name: DNR Hartman State 11-16
Location ID: 320317



Photo 5 Crude oil tanks

Photo 6 Sep