

Inspection Photos
Location Name: Badger oil1
Location ID: 320339



Photo 1 PU



Photo 2 WH Stained soil

Inspection Photos
Location Name: Badger oil1
Location ID: 320339



Photo 3 Unused flowback tank



Photo 4 TNK BTRY stained soil in front of crude oil tank.

Inspection Photos
Location Name: Badger oil1
Location ID: 320339



Photo 5 Stained soil under crude oil load out line



Photo 6 Produced water tank no placard

Inspection Photos
Location Name: Badger oil1
Location ID: 320339



Photo 7 trash inside sep house



Photo 8 Loc pit does not have 2' of free board

Inspection Photos
Location Name: Badger oil #1
Location ID: 320339



Photo 9 third larger pit



Photo 10 third larger pit