

Final Reclamation Inspection

October 4, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-23893

Inspection Document #: 682404048

Weld County, CO

SENE Section 36 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TJADEN #36-14
API: 05-123-23893



Photo 1. Photo taken from the well location, facing East. Weedy, annual vegetation was observed at the location and throughout the entire well access road. It is unclear whether reclamation took place for the access road, as gravel was observed throughout. The offsite shared Tank Battery is still active.



Photo 2. Photo taken from a portion of the access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: TJADEN #36-14
API: 05-123-23893



Photo 3. Photo taken from a portion of the access road, facing West. See comments under Photo 1.