

# *Inspection Photos*

*API#081-05704*

*Operator: Wexpro*

*Inspection Number: 692400195*

*Inspection Date: 9/26/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to North. Insert is close up of ground conditions.

September 26 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Wexpro PA State API#081-05704





**Photo#2:**

Overview of South Section of Location. Insert is close up of ground conditions.

September 26 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Wexpro PA State API#081-05704





Photo#3:  
Debris remains on site



Photo#4:

September 26 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Wexpro PA State API#081-05704





Photo#5:  
Debris remains on site.



Photo#6:

September 26 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Wexpro PA State API#081-05704





Photo#7:  
View of access road.



Photo#8:

September 26 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Wexpro PA State API#081-05704