



Photo#1:
View North over Location Center

September 26, 2018



Photo#2:
View South over Location Center



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Samson Res PA Rattlesnake State API#081-07202



Photo#3:
View East over Location Center



Photo#4:
View West over Location Center

September 26, 2018